The automatic calcimeter must be placed	on a flat,	horizontal	and clean	work surface	e, under a	3
hood or in a well ventilated area.						

It must not be subjected to vibration or shock.

For optimum performance, the temperature should be maintained at 20 $^{\circ}$ C + / - 2 $^{\circ}$ C.

The carousel must be perfectly positioned on the turntable in order to not slip during rotation.

The electronic scales is connected to calcimeter by RS232 cable.